

**DEPARTMENT FOR COMMUNITIES AND SOCIAL INCLUSION: ANNUAL  
ASBESTOS RISK REDUCTION REPORT 2014/15**

Category	Number of Sites		Category Description	Interpretation One or more items at these sites
	At start of year	At end of year		
1	0	0	Remove	Should be removed promptly
2	0	0	Remove as soon as practicable	Should be scheduled for removal at a practicable time
3	0	2	Use care during maintenance	May need removal during maintenance works
4	4	2	Monitor condition	Has asbestos present. Inspect according to legislation and policy
5	3	2	No asbestos identified / identified asbestos has been removed	All asbestos identified as per WH&S Regulations 2012 (Chapter 8 - Asbestos) has been removed
6	43	43	Further information required	These sites not yet categorised or some asbestos items do not have recommended actions

**Definitions:**

Category: The site performance score, determined by the worst item performance score at each site.

Number of Sites in Category: A count of how many sites have the corresponding site performance score, with separate counts done at the start and the end of each year.

Category Description: Indicates the recommended action corresponding to the worst item performance score (recorded in the asbestos register by a competent person, as per WH&S Regulations 2012 (Chapter 8 - Asbestos)).

Interpretation: A brief real-world example of what each category implies for a site.

**Additional Information**

*Please provide any further commentary to describe achievements for the year, and ongoing works and policies.*

